

Grumpy's Repair Inc.
 225 H Street
 Baker City, OR. 97814
 Phone: 541-523-3200 Fax: 541-523-1520
 Grumpy's It's Only A Name

INVOICE

28795

INVOICE

Printed Date: 01/31/2024

Work Completed: 01/31/2024

Baker County Library
 2400 Resort Street
 Baker City, OR 97814
 Office 406-539-3700 ED
 Home 541-523-6419

2002 Matthews/Freightliner -

Lic # : E226802

Odometer In : 288979

VIN # : 4UZ3CFAAX XCA66464

Hat # : 7323

Part Description	Qty	Sale	Ext	Labor Description	Ext
Complete Long Block with Turbo and Injectors	1.00	17,967.03	17,967.03	Labor to remove and install the engine, transmission and all accessories.	6,525.00
Freight	1.00	32.00	32.00	Cleaned engine compartment	
Radiator Hose	2.00	31.17	62.34	Labor performed: Grind large single step flywheel.	140.00
Curved Radiator Hose	1.00	114.97	114.97	Complete rebuild, removed tanks, cooked out, rodded out and re soldered headers.	650.00
Serpentine Belt	1.00	129.42	129.42	Remove and replace both rear shocks.	145.00
Air Filter (Gold)	1.00	72.73	72.73	Removed and replace both front shocks.	145.00
Radiator Cap	1.00	12.10	12.10	Re - pack and R&R rotor hub assembly, front brake rotors were under spec. Removed old rotors from hub assembly installed new rotors and installed bearing races, turned rotors, greased and installed rotors with brake pads.	290.00
Hose Clamp - (#16)	6.00	3.00	18.00	Remove and Replaced Spring Bushings and Hangers.	1,160.00
Hose - Heater - Silicone/Rubber 1" (ft)	15.00	26.95	404.25	Labor to pull drive shafts. Install both rear u-joints and one carrier bearing.	507.50
Cable / Zip Tie 14" Black	14.00	1.50	21.00	Labor to re seal transmission and install rebuilt shift tower.	580.00
Upper Radiator Hose	1.00	22.27	22.27	Labor to replace the cord for the block heater.	n/c
Upper Radiator Coolant Hose	1.00	60.17	60.17	Tested block heater.	
Clutch	1.00	696.68	696.68	Labor to replace the terminal end on the power cable.	36.25
Clutch Pilot Bearing	1.00	79.15	79.15	Replaced the hood stop cable.	36.25
Rear Shocks	2.00	81.65	163.30	Fixed the bush hood latches, so they would stop rattling.	217.50
Front Shocks	2.00	148.32	296.64		
Hub Caps	2.00	35.57	71.14		
Inner Bearing Cone	2.00	69.98	139.96		
Inner Bearing Cup	2.00	39.48	78.96		
Outer Bearing Race	2.00	50.82	101.64		
Outer Bearing Race -	2.00	24.98	49.96		
Front Wheel Hub Seals	2.00	67.73	135.46		
Front Brake Pads	1.00	352.72	352.72		
Front Rotors	2.00	238.94	477.88		
Rear Spring Bushings	2.00	61.22	122.44		
Center Carrier Bearing Assembly	1.00	169.39	169.39		
Rear U-Joints	2.00	147.82	295.64		
Loc Tite	1.00	5.00	5.00		
Gear Oil 80W-90 (qt) Size: QT	1.00	11.25	11.25		
Black Electrical Tape (Roll)	1.00	2.55	2.55		
Hose Clamp - (#6) Size: HS 1/4" - 7/16"	4.00	2.85	11.40		
Washer Solvent	1.00	141.65	141.65		
Bolt, 3/8" Hex Head - Grade 8	8.00	2.38	19.04		
Freeze Plug	1.00	1.52	1.52		
Cable / Zip Tie 8" Black	4.00	1.00	4.00		
Oil SAE 15 W 40 (gal)	3.75	39.15	146.81		
Coolant/Antifreeze - Green (gal)	7.00	19.75	138.25		
Ultra Black Size: 3.5 OZ	1.00	19.25	19.25		

Visit us on the web: www.grumpysrepair.com

Email Address: jr@grumpysrepair.com

Grumpy's Repair Inc.

225 H Street
 Baker City, OR. 97814
 Phone: 541-523-3200 Fax: 541-523-1520
 Grumpy's It's Only A Name

INVOICE

28795

INVOICE

Printed Date: 01/31/2024

Work Completed: 01/31/2024

Baker County Library
 2400 Resort Street
 Baker City, OR 97814
 Office 406-539-3700 ED
 Home 541-523-6419

2002 Matthews/Freightliner -

Lic #: E226802

Odometer In : 288979

VIN #: 4UZ3CFAAX XCA66464

Hat #: 7323

Part Description	Qty	Sale	Ext	Labor Description	Ext
Carb Kleen (can)	14.00	12.75	178.50		
Grease Xtrm (Tube)	1.00	14.75	14.75		
Hose Clamp - (#28) Size: HS 1 5/16" - 1 5/8"	2.00	2.85	5.70		
Solder Pellet - 2 Gauge - Orange	1.00	5.75	5.75		
Hose - Heater 3/4" ID (ft)	0.50	3.50	1.75		
6MM Washer	4.00	0.70	2.80		
6MM Bolt	2.00	2.50	5.00		
Fuel Filter (Gold)	1.00	27.58	27.58		
Battery & Starter Cable Copper Lug 3/8" 1 ga	1.00	4.75	4.75		
Transmission Reseal Kit	1.00	158.34	158.34		
Transmission Shift Tower with Shifter (Please note that this price could be lower we need casting # to be sure	1.00	1,320.00	1,320.00		
Cord Replacement for the Block Heater	1.00	52.02	52.02		
Primary Wire Ring Terminal 6 ga 3/8"	2.00	15.90	31.80		
1/8 Cable (FT)	3.00	7.00	21.00		
1/8 Cable ferrules	2.00	4.00	8.00		
Hose Clamps Quick Release #188	1.00	7.54	7.54		
Heat Shrink Tubing - Red - 18-20 ga (4.5" Lgth)	0.50	0.95	0.48		
Shop Supplies			5.00		

*Ed wants to
 deliver the
 Check*

*Ed reviewed + approved the
 increase in final cost of \$ 576.64
 - replaced rotors + brakes
 (highlighted items)
 Ch 1/31/2024*

[Payments -]

*Bid # 34,354.58
 Board Approved \$45,000*

I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is six months or 6,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Labor:	9,642.50
Parts:	24,498.72
Sublet:	790.00
Sub:	34,931.22
Tax:	0.00
Total:	\$34,931.22
Bal Due:	\$34,931.22

Vehicle Received: 1/31/2024

Signature _____ Date 1/31/24

Customer Number : 2567

Visit us on the web: www.grumpysrepair.com

Email Address: jr@grumpysrepair.com